

TOMINGLEY GOLD PROJECT

Monthly Environmental Monitoring Report

June 2017



TOMINGLEY GOLD PROJECT

Monthly Environmental Monitoring Report

June 2017

Document History

DATE	VERSION	REASON FOR CHANGE	AUTHOR
	Rev 1	Submitted for Information	СН

Table of Contents

1.	INTRODUCTION AND SCOPE	4
2.	WEATHER FOR MONTH 2017	4
,	A. Weather Station Data	4
3.	MONITORING LOCATIONS	6
4.	AIR QUALITY MONITORING	7
ļ	A. PM10 Monitoring	7
[B. Depositional Dust	9
(C. High Volume Air Sampler - Total Suspended Particulates	9
5.	NOISE MONITORING	10
,	A. Real-Time Noise Monitoring	10
6.	SURFACE WATER MONITORING	11
,	A. Gundong Creek	11
E	B. Sedimentation Ponds	11
7.	GROUNDWATER MONITORING	11
8.	BLAST MONITORING	12
9.	RESIDUE STORAGE FACILITY	13
10.	. BIODIVERSITY MONITORING	13

1. Introduction and Scope

This Monthly Environmental Monitoring Report has been prepared to collate environmental monitoring data undertaken for the Tomingley Gold Project during the month of June 2017.

This report also compares data collected to targets and provides commentary on environmental issues during the month.

2. Weather for May 2017

A. Weather Station Data

TGO WEATHER DATA IS PRESENTED BELOW.

Figure 1. June 2017 wind rose




Figure 2. Rainfall June 2017

June 2017	Rainfall (mm)
June 7	0.2
June 19	0.2
June 21	0.2
June 24	0.2
June 28	0.4
June 29	0.4
Total Rainfall	1.6

3. Monitoring Locations

FIGURE 3 indicates the location of where monitoring is undertaken for the project. Any additional monitoring undertaken will be discussed within the body of this report.

Figure 3. TGO water and vegetation monitoring points




Figure 4 indicates the location of environmental and survey monitoring points on and around the Residue Storage Facility.




Figure 4. Residue Storage Facility monitoring points

4. Air Quality Monitoring

A. PM10 Monitoring

PM10 is measured via a Tapered Element Oscillating Microbalance (TEOM) located at the southern edge of the Tomingley Village. This machine transmits real-time data via the internet to a computer located on site.

The Performance Criteria for PM10 has been set at an Annual Average of 30ug/m³ and a 24-Hour Average of 50ug/m³.

The 24 hour average limit was not exceeded during June.

The annual average at the end of May was 17.8ug/m³, well below the license limit.

Figure 5. TEOM Data June 2017


24 Hr Averages **Running Average** Date Comment (µg/m3) 1/06/2017 14.5 17.1 2/06/2017 22.0 17.1 3/06/2017 24.1 17.1 4/06/2017 16.7 17.2 5/06/2017 22.0 17.2 6/06/2017 23.6 17.3 7/06/2017 14.5 17.3 8/06/2017 10.9 17.3 15.7 9/06/2017 17.3 10/06/2017 7.6 17.3 11/06/2017 9.5 17.3 12/06/2017 11.6 17.3 13/06/2017 15.3 17.3 10.3 17.3 14/06/2017 15/06/2017 16.4 17.3 16/06/2017 20.1 17.4 17/06/2017 21.1 17.4 18/06/2017 NA 17.4 Insuffucient data 19/06/2017 26.4 17.5 20/06/2017 16.4 17.5 21/06/2017 27.7 17.6 22/06/2017 14.1 17.6 23/06/2017 18.0 17.6 24/06/2017 17.0 17.6 25/06/2017 22.5 17.7 26/06/2017 13.7 17.7 27/06/2017 18.9 17.7 28/06/2017 29.2 17.8 29/06/2017 20.3 17.8 30/06/2017 21.7 17.8 1-hour average data used 18.0 Average 24 Hour Criteria Exceedance

Note: For comparison purposes, highlighted results indicate levels above the EPA and NEPM 24-hour maximum criteria for PM₁₀

B. Depositional Dust

Depositional Dust monitoring undertaken during this month returned the results indicated in the table below. The performance criteria for deposited dust is averaged over 12 months.

Figure 6. Dust Deposition Results 2015 - 2017




C. <u>High Volume Air Sampler - Total Suspended Particulates</u>

High Volume Air Sampling (HVAS) for Total Suspended Particulates (TSP) was undertaken this month. Figure 7 below provides the results.

The performance criteria for TSP is averaged over 12 months

Figure 7. Hi-Volume Air Sampler Data 2015 - 2017




5. Noise Monitoring


A. Real-Time Noise Monitoring

See real-time noise monitoring data presented below.

Figure 8. TGO Noise Monitoring 1/6/2017 - 30/6/2017



Location	Start Time	End Time	Activity	LDN (dB)	L _{Aeq} (dB)	L _{AF} (dB)	L _{AMin} (dB)	L _{A10} (dB)	L _{A50} (dB)	L _{A95} (dB)
Brooklands	1/06 12:00:00 AM	30/06 12:00:00 AM	100%	47.6	47.6		21.9	48.3	41.9	33.1



6. Surface Water Monitoring

A. Gundong Creek

Gundong Creek did not flow during June and as such, no water sampling was undertaken.

B. Sedimentation Ponds

Sediment basins did not experience any discharges during the month of June.

7. Groundwater Monitoring

Groundwater was undertaken during June in line with license requirements.

Results from this round of monitoring fell within expected limits.

A further round of monitoring is scheduled in for September.

8. Blast Monitoring

Blasts are carried out in all open cut pits and vibration and decibels are monitored from several locations. Below are the vibration results recorded from the monitors at Hart's Cottage and Tomingley Village.

Figure 9. Blast Monitoring

EventKey	Date/Time	Max R (mm/s)	Location
78342	1/06/2017 13:09		Harts Cottage
78342	1/06/2017 13:09	0.12	Tomingley Village
78375	2/06/2017 13:06		Harts Cottage
78375	2/06/2017 13:06	0.61	Tomingley Village
78391	3/06/2017 13:01		Harts Cottage
78391	3/06/2017 13:01	0.06	Tomingley Village
78412	5/06/2017 13:05	0.24	Harts Cottage
78412	5/06/2017 13:05	0.3	Tomingley Village
78413	5/06/2017 13:16	0.05	Harts Cottage
78413	5/06/2017 13:16	0.06	Tomingley Village
78418	5/06/2017 13:20	0	Harts Cottage
78418	5/06/2017 13:20	0	Tomingley Village
78445	6/06/2017 13:06	0.08	Harts Cottage
78445	6/06/2017 13:06	0.1	Tomingley Village
78490	9/06/2017 11:09	0.18	Harts Cottage
78490	9/06/2017 11:09	0.22	Tomingley Village
78518	10/06/2017 12:57		Harts Cottage
78518	10/06/2017 12:57	0.14	Tomingley Village
78546	13/06/2017 14:21	0.13	Harts Cottage
78546	13/06/2017 14:21	0.15	Tomingley Village
78558	14/06/2017 14:59		Harts Cottage
78558	14/06/2017 14:59	0.54	Tomingley Village
78571	15/06/2017 13:01		Harts Cottage
78571	15/06/2017 13:01	0.06	Tomingley Village
78599	16/06/2017 13:10		Harts Cottage
78599	16/06/2017 13:10	1.42	Tomingley Village
78635	17/06/2017 14:04		Harts Cottage
78635	17/06/2017 14:04	0.15	Tomingley Village
78647	19/06/2017 12:59		Harts Cottage
78647	19/06/2017 12:59	0.14	Tomingley Village
78721	21/06/2017 12:58		Harts Cottage
78721	21/06/2017 12:58	0.14	Tomingley Village
78888	23/06/2017 16:49	0.18	Harts Cottage
78888	23/06/2017 16:49	0.34	Tomingley Village
78946	24/06/2017 12:05	0.01	Harts Cottage
78946	24/06/2017 12:05	0.02	Tomingley Village
78938	26/06/2017 12:58	0.11	Harts Cottage
78938	26/06/2017 12:58		Tomingley Village
78969	27/06/2017 13:05	0.42	Harts Cottage
78969	27/06/2017 13:05		Tomingley Village
78991	28/06/2017 13:59		Harts Cottage
78991	28/06/2017 13:59	0.14	Tomingley Village

9. Residue Storage Facility

Residue from the processing plant is discharged into the Residue Storage Facility or RSF. The Environmental Protection Licences dictates that the Weak Acid Dissociable (WAD) Cyanide found in this residue must be less than 20 milligrams per litre for 90% of the time and less than 30 milligrams per litre for 100% of the time.

WAD cyanide discharge levels are shown below with the maximum reading well below the 100th percentile limit of 30ppm.

Monthly average: 4.38 ppm

Daily maximum: 9.65 ppm on 4th June
 Daily minimum: 0.85 ppm on 28th June

• Number of exceedances: zero

10. Biodiversity Monitoring

Fauna deaths:

• There were no fauna deaths in the RSF for the month.

Vertebrate pests

A program of trapping feral cats and foxes has continued with no animals being caught during June.